

Notes recorded by DEQ while overseeing the operation of the FPRS indicate that more than one upset events likely occurred. For example:

Commented [SGH1]:

-- Does the nature of the contaminants (a mixture of heavy oil and diesel, with recorded observations of high viscosity and a high degree of "stickyness") support the possible explanations above?

Commented [SGH2]: Soil type in area of Test Pit 4?